




축전지 점검결과

점검일	2023. 01. 31	점검형태	화재예방 점검
업체명	영종도 자기부상철도 파라다이스시티역	온도(°C)	12.6~13.4
담당자/연락처	이진수팀장/	충전전압(V)	269.2
용도,장소	통신기계실, UPS용	AC(A) / DC(A)	1.3/-1.3~1.7
제품명	ESP40	내부저항(mΩ) 기준(참고)	
수량(EA)	20EA	점검결과	
LOT	2021.06.03		
셀	전압(V)	내부저항(mΩ)	비고
1	13.46	8.98	#DIV/O!
2	13.47	9.63	#DIV/O!
3	13.49	8.74	#DIV/O!
4	13.43	9.22	#DIV/O!
5	13.41	9.36	#DIV/O!
6	13.41	9.84	#DIV/O!
7	13.47	8.75	#DIV/O!
8	13.51	9.67	#DIV/O!
9	13.49	9.69	#DIV/O!
10	13.52	9.13	#DIV/O!
11	13.4	8.86	#DIV/O!
12	13.48	9.75	#DIV/O!
13	13.46	8.9	#DIV/O!
14	13.41	8.73	#DIV/O!
15	13.39	9.24	#DIV/O!
16	13.45	8.76	#DIV/O!
17	13.45	10.27	#DIV/O!
18	13.52	9.5	#DIV/O!
19	13.48	9.08	#DIV/O!
20	13.42	9.17	#DIV/O!
평균	13.46	9.264	#DIV/O!
설치업체 / 일자		설치상태(배열,극성,체결상태)	4단2열
점검내용		제품 외관상태(누액,파손여부등)	
		마킹 실시여부	
운영환경	냉방기 소형 미가동	취급설명서 유무	
		기타	
설치 장소		Lot/배열/극성	

볼트제결 /마킹유무		취급설명서 부착 유무	
---------------	---	----------------	--

기타 (전지상태, 환경등)	<p>※타사품 재원전원(Ni-MH 액식전지) EVM600P(120929)*182EA</p> 		
----------------------	--	--	---